

Such defects as have been discovered have been the result, not of an intention to defraud, but the result of carelessness both on the contractor and the State engineering personnel.

Sub-grade stabilization on 1st big job--carelessness

Doesn't think Cone trying to cheat--if he had he would have done it from one end to the other--some work excellent

.....--this one place, too thick elsewhere--or too wide.